

A wide-angle photograph of a city skyline at night, viewed from across a body of water. The buildings are illuminated with various lights, and their reflections are visible on the water's surface. The sky is dark blue. The text 'Yukon Infrastructure Warnings' is overlaid in white on the left side of the image.

# Yukon Infrastructure Warnings



Powering Business Worldwide

© 2022 Eaton. All rights reserved.

# Infrastructure Warnings Categories

Gateway / Relay Communication Warnings

Gateway Enclosure Warning

Gateway Operation Warnings

Gateway Power Warnings

Mesh Network Warnings

Power Line Carrier Warnings

# Gateway / Relay Communication Warnings

Gateway Connection Status Warning

Relay Outage Event Warning

# Gateway Communication Status Warning

## Infrastructure Warnings

Gateways: 0 2      Relays: 2 0  
CCUs: 4 3      Repeaters: 3 3

**Most Recent Active Issues:** [View Details](#)

Name	Status	Duration
Gateway 1	Gateway communications interrupted since 01/19/2022 12:35:56	10 min.

# Gateway Communication Status Warning

**Yukon**



**Gateway**







# Gateway Communication Status Warning

## Yukon




## Gateway






# Gateway Communication Status Warning

## Yukon




- ✓ Gateway hardware or software failure

## Gateway




# Gateway Communication Status Warning

## Yukon




- ✓ Gateway hardware or software failure
- ✓ Backhaul failure due to:
  - ✓ A bad ethernet cable

## Gateway




# Gateway Communication Status Warning

## Yukon




- ✓ Gateway hardware or software failure
- ✓ Backhaul failure due to:
  - ✓ A bad ethernet cable
  - ✓ Issue with backhaul cell modem

## Gateway




# Gateway Communication Status Warning

## Yukon



- ✓ Gateway hardware or software failure
- ✓ Backhaul failure due to:
  - ✓ A bad ethernet cable
  - ✓ Issue with backhaul cell modem
  - ✓ Issue with backhaul switch

## Gateway




# Gateway Communication Status Warning

## Yukon



- ✓ Gateway hardware or software failure
- ✓ Backhaul failure due to:
  - ✓ A bad ethernet cable
  - ✓ Issue with backhaul cell modem
  - ✓ Issue with backhaul switch
  - ✓ Cell modem carrier communication interruption

## Gateway



# Gateway Communication Status Warning

## Yukon



- ✓ Gateway hardware or software failure
- ✓ Backhaul failure due to:
  - ✓ A bad ethernet cable
  - ✓ Issue with backhaul cell modem
  - ✓ Issue with backhaul switch
  - ✓ Cell modem carrier communication interruption
  - ✓ Customer network issue

## Gateway



# Gateway Communication Status Warning

## Yukon



- ✓ Gateway hardware or software failure
- ✓ Backhaul failure due to:
  - ✓ A bad ethernet cable
  - ✓ Issue with backhaul cell modem
  - ✓ Issue with backhaul switch
  - ✓ Cell modem carrier communication interruption
  - ✓ Customer network issue
- ✓ Power lose to the gateway

## Gateway



# Gateway Communication Status Warning

## Infrastructure Warnings

Gateways: 0 2      Relays: 2 0  
CCUs: 4 3      Repeaters: 3 3

**Most Recent Active Issues:** [View Details](#)

Name	Status	Duration
------	--------	----------



# Relay Outage Event Warning

## Infrastructure Warnings


Gateways: 0 2      Relays: 2 0  
CCUs: 4 3      Repeaters: 3 3

**Most Recent Active Issues:** [View Details](#)

Name	Status	Duration
Relay 1	An outage notification has been received	10 min.

# Relay Outage Event Warning

## Yukon



✓ Power is lost to the relay

